

Summary Report

SESSION DETAILS

Box ID	0000000001096803
Start Time	2026-02-20 12:12:22
End Time	2026-02-20 12:13:56

KEY PERFORMANCE INDICATORS

Metric	Value
Pick Attempts	33
Successful Picks	24
Interlayer Picks	0
PPH	1198
Avg Cycle Time (s)	3

ANOMALY CLIPS (9)

#	Anomalies	Start	End	Anomaly Clips
1	MISPICK	2026-02-20 12:12:22	2026-02-20 12:12:23	—
2	DOUBLE_PICK	2026-02-20 12:12:44	2026-02-20 12:12:47	Click here
3	MISPICK	2026-02-20 12:12:47	2026-02-20 12:12:52	Click here
4	MISPICK	2026-02-20 12:13:33	2026-02-20 12:13:35	Click here
5	DOUBLE_PICK	2026-02-20 12:13:41	2026-02-20 12:13:43	Click here
6	MISPICK	2026-02-20 12:13:44	2026-02-20 12:13:46	Click here
7	DOUBLE_PICK	2026-02-20 12:13:49	2026-02-20 12:13:52	Click here
8	DOUBLE_PICK	2026-02-20 12:13:53	2026-02-20 12:13:55	Click here
9	DOUBLE_PICK	2026-02-20 12:13:56	2026-02-20 12:13:58	Click here

Total Anomalies: 9

PERFORMANCE SUMMARY

- Order Fulfillment Request : 31
- Process achieved a 72.7% success rate with 24 of 33 cycles completed successfully.
- All 24 successful cycles were completed on-time.
- The anomaly resulted in 4 missed pick(s) during the session.
- Double pick detected 5 time(s).
- Retry attempts: 4.
- PPH: 1198 picks per hour.
- Average cycle time: 3.0s.
- Order status: 24/31.
- Overall performance remains stable with minimal timing deviations.