

# Box Analytics Report

## BOX DETAILS

Box ID	1096803
Start Time	2026-02-12 12:12:22
End Time	2026-02-12 12:12:22
Video URL	<a href="#">Click here</a>

## KEY PERFORMANCE INDICATORS

Metric	Value
Inducting Count	31
Pick Attempts	33
Successful Picks	24
Interlayer Picks	0
Total Anomalies	9
PPH	1198
Avg Cycle Time (sec)	3

## ANOMALY CLIPS (9)

#	Anomalies	Start	End	Anomaly Clips
1	MISPICK	2026-02-12 12:12:22	2026-02-12 12:12:23	—
2	DOUBLE_PICK	2026-02-12 12:12:44	2026-02-12 12:12:47	<a href="#">Click here</a>
3	MISPICK	2026-02-12 12:12:47	2026-02-12 12:12:52	<a href="#">Click here</a>
4	MISPICK	2026-02-12 12:13:33	2026-02-12 12:13:35	<a href="#">Click here</a>
5	DOUBLE_PICK	2026-02-12 12:13:41	2026-02-12 12:13:43	<a href="#">Click here</a>
6	MISPICK	2026-02-12 12:13:44	2026-02-12 12:13:46	<a href="#">Click here</a>
7	DOUBLE_PICK	2026-02-12 12:13:46	2026-02-12 12:13:53	<a href="#">Click here</a>
8	DOUBLE_PICK	2026-02-12 12:13:53	2026-02-12 12:13:55	<a href="#">Click here</a>
9	DOUBLE_PICK	2026-02-12 12:13:56	2026-02-12 12:13:59	<a href="#">Click here</a>

Total Anomalies: 9

## PERFORMANCE SUMMARY

- Order Fulfillment Request : 31
- Order status: 24/33.
- Process achieved a 72.7% success rate with 24 of 33 cycles completed successfully.
- All 24 successful cycles were completed on-time.
- The anomaly resulted in 4 missed pick(s) during the session. Retry attempts: 4.
- Double pick detected 5 time(s).
- PPH: 1198 picks per hour.
- Average cycle time: 3.0s.
- Overall performance remains stable with minimal timing deviations.