

## Summary Report

### SESSION DETAILS

Box ID	00000000001096803
Start Time	2026-02-20 12:12:22
End Time	2026-02-20 12:13:56

### KEY PERFORMANCE INDICATORS

Metric	Value
Pick Attempts	33
Successful Picks	24
Missed Picks	4
Interlayer Picks	0
PPH	1198
Avg Cycle Time (s)	3

### ANOMALY CLIPS (9)

#	Start	Anomaly Clips
1	2026-02-20 12:12:22	—
2	2026-02-20 12:12:44	<a href="#">Click here</a>
3	2026-02-20 12:12:47	<a href="#">Click here</a>
4	2026-02-20 12:13:33	<a href="#">Click here</a>
5	2026-02-20 12:13:41	<a href="#">Click here</a>
6	2026-02-20 12:13:44	<a href="#">Click here</a>
7	2026-02-20 12:13:49	<a href="#">Click here</a>
8	2026-02-20 12:13:53	<a href="#">Click here</a>
9	2026-02-20 12:13:56	<a href="#">Click here</a>

## PERFORMANCE SUMMARY

- Order Fulfillment Request : 31
- Process achieved a 72.7% success rate with 24 of 33 cycles completed successfully.
- All 24 successful cycles were completed on-time.
- The anomaly resulted in 4 missed pick(s) during the session.
- Double pick detected 5 time(s).
- Retry attempts: 4.
- PPH: 1198 picks per hour.
- Average cycle time: 3.0s.
- Order status: 24/31.
- Overall performance remains stable with minimal timing deviations.