



A/C Model #	A320	 FRONTAL SHEET	GAT Control No	MPD-005
A/C Reg. #	VT-IJX		Task #	215000-03-2
Exec Doc #	HMV24/000281/0125			

Execution Document #	HMV24/000281/0125	CR Category	NA
		Inspection category (CMR/CDCCL/FTS)	NA
Task #	215000-03-2	Regulatory	DGCA
			
Title	PACK RAM AIR INLET DETAILED INSPECTION OF ACTUATOR MECHANISM AND INLET FLAP FOR EXCESSIVE PLAY AND CHECK GAP BETWEEN INLET NOSE AND DIFFUSER RAMP		

Main Task Details

Task Type	Category	ATA #	Source Doc #	Man hours
MPD	DET	21		2.30

ETOPS

YES NO

Access Panel

Access Panel
NA

Zones

Zones
100

Skill Requirements

Skill Code	Skill Description
B1	B1 MAINTENANCE CERTIFICATION

Tools Requirements

Tool Part #	Description	Quantity	Serial #	Calibration Due Date
98A24403000000	STRAP-CABLE RESTRAINT			

Component Replacement

Off Part #	On Part #	Off Serial #	On Serial #	Part Description	UOM	Position



A/C Model #	A320	 FRONTAL SHEET	GAT Control No	MPD-005
A/C Reg. #	VT-IJX		Task #	215000-03-2
Exec Doc #	HMV24/000281/0125			

Component Replacement

Off Part #	On Part #	Off Serial #	On Serial #	Part Description	UOM	Position

Parts Requirements

Ref Document #	Part #	Description	Serial #	Quantity	UOM	GRN / Release #

Finding/Discrepancy (tick one) YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>	Cross Reference(s):
Independent Inspection:	
<input type="checkbox"/> Independent Inspection	
1st Inspection/1st Person: _____ (Signature)	Stamp _____ (Date & Time) _____
2nd Inspection/2nd Person: _____ (Signature)	Stamp _____ (Date & Time) _____
CRS Statement:	
F/HYD/GACAEL/1055 CERTIFIES THAT THE WORK SPECIFIED EXCEPT AS OTHERWISE SPECIFIED WAS CARRIED OUT IN ACCORDANCE WITH CAR 145 AND IN RESPECT TO THAT WORK THE AIRCRAFT/ AIRCRAFT COMPONENT IS CONSIDERED READY FOR RELEASE TO SERVICE.	
AME (SIGN & STAMP)	DATE
 	7/1/25

AIRBUS	JOB CARD PACKAGE TITLE: 2C CHECK	IGO - Tail Number - MSN - FSN VT-IJX - 09559 - 501
2C CHECK		

MPD	Reference	Title	DocType
215000-03	21-61-51-200-001-A	Detailed Inspection of Actuator Mechanism and Inlet Flap for Excessive Play and Check Gap between Inlet Nose and Diffuser Ramp	AMM

Job Cards Package is made of: 1 job cards.

ANY FINDINGS

YES	<input checked="" type="checkbox"/> NO
-----	--

IRC No. : Nil

J
21/1/25



JCP Title: 2C CHECK	CERTIFICATE OF TASK / INSPECTION COMPLETION: CERTIFIES THAT THE TASK / INSPECTION HAS BEEN COMPLETED TO THE REQUIRED STANDARD AND SUPPORTS THE FINAL MAINTENANCE RELEASE / CERTIFICATE OF RELEASE TO SERVICE	Page 1 of 2 PRINT DATE: Jan 01/2025
---------------------	--	--

AIRBUS	JOB CARD PACKAGE TITLE: 2C CHECK	<u>IGO -</u> Tail Number - MSN - FSN VT-IJX - 09559 - 501
2C CHECK		

INTENTIONALLY LEFT BLANK

JCP Title: 2C CHECK	CERTIFICATE OF TASK / INSPECTION COMPLETION: CERTIFIES THAT THE TASK / INSPECTION HAS BEEN COMPLETED TO THE REQUIRED STANDARD AND SUPPORTS THE FINAL MAINTENANCE RELEASE / CERTIFICATE OF RELEASE TO SERVICE	Page 2 of 2 PRINT DATE: Jan 01/2025
---------------------	--	--

